

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

673
ESE
1/2-1
0.981 mi.
5181 ft.

CLOSED-LACKOF RECENT INFO
3115 BRIGHTON 6TH STREET
BROOKLYN, NY

NY LTANKS **S106703259**
NY AST **N/A**

Relative:
Higher

Actual:
9 ft.

LTANKS:

Name: CLOSED-LACKOF RECENT INFO
Address: 3115 BRIGHTON 6TH STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 8803751 / 2003-03-05
Facility ID: 8803751
Site ID: 62137
Spill Date: 1988-07-29
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: ADMIN. CLOSED
Referred To: Not reported
Reported to Dept: 1988-07-29
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1988-08-02
Spill Record Last Update: 2003-03-14
Spiller Name: Not reported
Spiller Company: BEN JOSH MGNT
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extension: Not reported
DEC Region: 2

DER Facility ID: 60277
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
ADMIN.CLOSED 03/05/2003- Closed Due To The Nature / Extent Of The
Spill Report"

Remarks: "5K TANK FAILED INITIAL SYTEM- PETRO TITE TEST, COULDN'T MAINTAIN
LEVELIN STANDPIPE, MAY BE PROBLEM WITH 3 INCH LINE, WILL EXCAVATE,
ISOLATE AND RETEST.CLOSED DUE TO LACK OF ANY RECENT INFO- DOES NOT
MEET ANY CLEAN UP REQUIREMENTS."

All TTF:

Facility ID: 8803751
Spill Number: 8803751
Spill Tank Test: 1534374
Site ID: 62137
Tank Number: Not reported
Tank Size: 0
Material: 0002
EPA UST: Not reported
UST: Not reported
Cause: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:

Site ID: 62137
Operable Unit ID: 918898
Operable Unit: 01
Material ID: 459285
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: L
Recovered: .00
Oxygenate: Not reported

AST:

Name: 3115 BRIGHTON 6 ST
Address: 3115 BRIGHTON 6TH STREET
City,State,Zip: BROOKLYN, NY 11235
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-211753
Program Type: PBS
UTM X: 587939.39293
UTM Y: 4492269.05920
Expiration Date: N/A
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 7732
Affiliation Type: Facility Owner
Company Name: 3115 REALTY CO
Contact Type: Not reported
Contact Name: Not reported
Address1: 247 SEELEY STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11218
Country Code: 001
Phone: (718) 965-1500
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2014-01-24

Site Id: 7732
Affiliation Type: Mail Contact
Company Name: 3115 REALTY CO
Contact Type: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Contact Name: CARL FRAIMAN
Address1: 247 SEELEY STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11218
Country Code: 001
Phone: (718) 965-1500
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2014-01-24

Site Id: 7732
Affiliation Type: Facility Operator
Company Name: 3115 BRIGHTON 6TH STREET
Contact Type: Not reported
Contact Name: ENVER NURDINOV
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 965-1500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 7732
Affiliation Type: Emergency Contact
Company Name: 3115 REALTY CO
Contact Type: Not reported
Contact Name: CARL FRAIMAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 965-1405
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank Id: 25082
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
E12 - Piping Secondary Containment - Double-Walled (AG only)
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.

Tank Type: Steel/Carbon Steel/Iron

Tank Status: Closed - In Place

Pipe Model: Not reported

Install Date: 01/01/1974

Capacity Gallons: 5000

Tightness Test Method: NN

Date Test: Not reported

Next Test Date: Not reported

Date Tank Closed: 01/28/2014

Register: True

Modified By: NRLOMBAR

Last Modified: 04/14/2017

Material Name: #2 fuel oil (on-site consumption)